er fillespirer erhelmsverse grænssingtryse i ogser	The state of the s	25
40 M . 10 temper	CLASSIFICATION 1.CP.ST-CONTROL/US OFFICE LIS ONLY	
	/ Tracoslevia Report No.	
70710	Airfield of Zenau	9
d file in spanners separately so		<u></u>
EVALUATION	ON PLACE OBTAINED 25X1 3	· D
DATE OF	CONTENT	
DATE OF	MANAD DAYE PREPARED 8 September 1949	-
RESERVAN		25
	S FNCLOSURES (No. 2 TYPE)	TO COMMENCY OF
	Document No.	Andrews .
KEMARKS.	This document is hereby regreded to NO CHANCE IN CLOSE	PRESIDENCE MOVES IN THE
Military Street and No. Shall are	CONFIDENTIAL III address from the	C
COT TO SECURITION OF ASSESSED	Director of Central Industrial States.	ST
	Next Review Date: 2008 . Date 2 3 MAY 1918 By	
	And the state of t	en transcapping on the second
	The ZEMAIN (W 19/Y 28) sirfield had a large number of building barrocks, and hangars. Assumition bunkers were built into a widge mouth of the surfield. The surrounding terrain was flaw only flight obstacles were the masts of a radio station, 2.5 miles from the field, and two 130-foot factory anchostacks of the "Theorem Aircraft Plant. The field was used for conversed and officery purposes. Tields, it was one of the largest and best equipped similarly was a chydrian administration to the military administration the was a chydrian administration and a permanent Soviet supervise complexion. The latter was also in charge of a large transmitting and receiving station, equipped with the latest sets which was located at the town border of BELGRADE.	25 s ຄອກຈ ຮັດໜ້າ
	a. The landing field, with a rolled grass surface, was expanded throw times to a final length of 9,000 feet and a width of 1,550 feet. A new drainage installation was completed by lote Earch 1949. The concrete runway, extending along the outline landing field, terminated in a taximay which ran in front of the two hangars, the repeir hangar and the flight control station on the northwestern edge of the field. Hangar I, a steel structure, was 50 x 100 x 650 feet, hangar	3

a corrugated sheet metal hangar of German make, was 40 x 100 m 250 feet. Two more bangars had been destroyed and the debris removed

b. All workshops, the foundry, the locksmith's stop, and the small smalling furnace were being equipped with novel machines of Cerman make by German engineers. This activity was, however, greatly hampered by the scenety of skilled workers. spare parts and machine parts. Because of the lock of spare parts numerous aircraft could not be repaired for days. German specialists repeatedly declared that the embirs work would come to a standstill unless Soviet or German motorial and spera part deliverios arrived.

CLASSIFICATION

3.COMERCIA PER OFFICE AND COMMUNICATION OF THE COMU

NEW TO COLUMN CENTRAL OF THE CONTRACT OF THE COLUMN STREET OF THE COLUMN

25X1

- 2. The cirfield had boundary lights, alternating red and white many lane, and red obstacle lights (lamps on radio masts of the Thanks Plant).
- E. Three large searchlights were in operation. The telecommunication center. Including the teletype and telephone stations, was housed in the flight control station was noused called and line townered. The weather station was noused in the tower of the same building. Some 20-rm subjectoraft game were ampleted to the west, near a gardener's establishment. Four 20-th ambinistraft can emplacements were located on the mountain slope to the north, above the samunition bunkers.
- 4. There was very heavy flying with comercial advaraft and regular trainers. Ath the exception of Greats and Muposlavs who had forcerly been trained in the Garnan Air Force, most flight instructors were Evilets. Accidents frequently occured. Three forces decreas Is-109 fighters were seen crashing in one Cap.
- 5. A former Common in Porce first lieutenent (a Greet) was CC of the phlot school. But there were still Woviet instruction officers in Earth 1949.
- 3. The flying achord comprised 600 trainers. Two thousand air force recruits were quartered in the barracks. Twenty-five to thirty aircraft of the following types were assigned to the flying school: TL-2s, Yaks, Me-100s, Ju-68s (used as transport aircraft and for parachuting), twin-engine "Douglas", some biplanes of Soviet make, two "Hentschel" hiplanes, one "Fiesslar Storch", and two "Taifun" sports planes.

25X1

25X1

Company: terant generally confirms the statements rade
The runnay is

4,600 feet lang.

Assembling to this report: Soviets were apparently still stablemed at the field in Parch 1949.

shootding to pravious reports, a flying school is located at the field. This assumption is surported by the various simports types parked at the airfield.

SECRET-CO INDI/US OFFICIALS OWLY

CONTINUE NAME

Approved For Release 2005/12/14: CIA-RDP82-00457R003400330006-6